

## Appendix D: Safety Related Warnings & Symbols

### General Warnings



#### Handling a battery

- Wear an appropriate eye-shield where required.



#### Handling battery electrolyte

- Wear an appropriate eye-shield where required.



#### Welding

- Wear an appropriate eye-shield where required.



#### Machines where there is any possibility of oil leaks You should keep a look-out for oil leaks. If there is an oil leak:

- 1 Put up barriers.
- 2 Spread oil- absorbent granules over the affected area.
- 3 Put a drip tray in place, if there is space.
- 4 Take steps to cure the cause of the leak.



#### Compressed air

- Compressed air is very dangerous: pressures as low as 68.94KN/M<sup>2</sup> (10 lb/in<sup>2</sup>) can penetrate into the body or blood stream and cause serious injury or death.
- Never misuse compressed airlines or use for unauthorised purposes, such as cleaning machines or clothes.
- Do not adjust relief valve setting without instruction from an engineering supervising officer.
- Do not disconnect snap connectors while the line is pressurised.



#### Hinged racks

- Check that the rack is stable when it is extended.